



# STRAINERS

## 192 Y strainer

### LOSS DIAGRAM (With water)

KV	2,20	3,40	3,80	7,20	11	13	15	28	77	93	146
----	------	------	------	------	----	----	----	----	----	----	-----

